




OK-5112H

**ASSEMBLY INSTRUCTION**

1. INDOOR USE ONLY
2. REPLACE THE BULB AFTER THE BULB GETS COOL.



**Assembly steps:**

**Step 1.** Turn threaded tube(B) to assembly(A), put assembly(C) over the threaded tube and secure with nut(D).

**Step 2. Mount ceiling fitting**

Step 2-1. Tighten loop(F) on the tube(G).

Step 2-2. Loosen screw(J) and pass canopy(H) over the tube(G).  
Step 2-3. Tighten loop(I) on the tube(G).

Step 2-4. Pass the main wire through the links of chain, loop(F), canopy(H), tube(G) and loop(I).

Step 2-5. Attach first link and last link(E) of chain to the loops(C1) and(F).

Step 2-6. Connect wire to the power supply cord.

Step 2-7. Raise the canopy(H) to ceiling and secure it by tightening the screw(J).

Step 2-8. Hang the Loop(I) on the hook on ceiling.

**Step 3.** Hang bead strings on the loop(A1). Hang bead(B1) on the hole

**Step 4.** Turn in the bulb to the socket.

After completed the above instruction, please check once more to ensure its safety. Then you may turn the power on. If the external cable or cord is damaged it shall be replaced by qualified person to avoid hazard.